EXHIBIT "9"

Repair Order Detail - Internal Copy

RO Number: 230221

RO Status: CLOSED

Customer: HOLLOWAY, ANTHONY HOYT Click to View Cust Copy Cell: **GRAY** Mileage: 2,228 Payment type: CHK, CC
Service advisor: 21472 Promised time: 05:00 PM
Tag number: T131 Promised date: 07/11/2016 Waiter: No Estimate: 0.00 Tag number: T131 Customer Comments: No CUSTOMER REQUESTS 4.5" LIFT INSTALLED. CUSTOMER SUPPLIED LIFT. CQL STEERING/SUSPENSION 9.50 731.50 Tech(s): 21772 21772 0.00 Lbr: 731.50 Other: 0.00 Total Line A: Story: 2228 INSTALLED 4.5" ROUGH COUNTRY LIFT, CUSTOMER SUPPLIED LIFT. AND INSTALLED DUAL STEERING STABILIZER. ALSO PROVIDED BY CUSTOMER. MOUNT AND BALANCE 4 FUEL 2PC MAVERICK 22X12 ON LT35X12.50R22 TOYO OPEN COUNTRY M/T. 46FOZ07 CQL MOUNT AND BALANCE 0.00 75.00 Tech(s): 16716 9L3Z*1700*A 4 KIT - VALVE 61.96 D26022201747 4 22X12 FUEL 2PC 2,120.00 MAVERICK R571848 1 INSTALL KIT
360540 4 LT35X12.50R22 TOY M/T
4,146.00 Lbr: 75.00 Other: 0.00 Total Line B: 48.00 1.916.04 4.221.00 Story: 2228 MOUNTED AND BALANCED 4 WHEELS ON TOYO OPEN COUNTRY M/T LT35X12.50R22. CUSTOMER REQUEST WHEEL ALIGNMENT 45FOZ CQL CUSTOMER REQUEST 2.00 95.00 WHEEL ALIGNMENT Tech(s): 21772 0.00 Lbr: 95.00 Other: Pts: 0.00 Total Line C: 95.00 Story: 2228 PERFORMED ALIGNMENT, SET VEHICLE TO ROUGH COUNTRY SPECS. ALL CHECKED GOOD AFTER TEST DRIVE. CUSTOMER REQUEST QUICK LANE MULTI POINT INSPECTION 99FOZZQ99P CQL CUSTOMER REQUEST 0.00 0.00 QUICK LANE MULTI POINT INSPECTION Tech(s): 21772 0.00 Lbr: 0.00 Other: Pts: 0.00 Total Line D: 0.00 Customer Pay Labor 901.50 Parts 4,146.00 Lube 0.00 Sublet 0.00 Miscellaneous/Shop Charge 30.00

Deductible

Total Charges

0.00

5,077.50

Repair Order Detail - Internal Copy

Less Insurance/Adjustment Sales Tax Total 0.00 292.32 5.369.82